

NZ 38(T)/25 NEW ZEALAND - North Island - West Coast - Port Taranaki. Dredged Area, Rocks

1. Mariners are advised that the depth of the dredged area at Berth 1 is temporarily reduced from 8.5m to 6.4m until further notice.
2. Underwater rocks have been identified in the following positions:

| | <i>Position</i> | <i>Depth</i> |
|-----|-----------------------------|--------------|
| (a) | 39°03'.366S., 174°01'.943E. | 9.5m |
| (b) | 39°03'.364S., 174°01'.939E. | 7.8m |
3. Mariners should contact the Harbourmaster for information on the latest depths.
4. Mariners are advised to exercise caution when navigating in the area.

Chart temporarily affected: NZ 4432Port Taranaki Ltd.
HITS 4432/189