## NZ 33(P)/25 NEW ZEALAND - North Island - East Coast - Whangārei Harbour. Depths, Shoreline Construction and Aids to Navigation

- 1. Former notice NZ 67(P)/22 is cancelled.
- 2. The latest survey (2022) in the vicinity of the channel west of Limestone Island indicates significant changes to charted depths. The most significant changes are as follows:

	Position	Depth
(a)	35°46'.939S., 174°21'.036E.	1.8
(b)	35°46'.970S., 174°20'.988E.	0.6
(c)	35°47'.001S., 174°20'.951E.	-0.2

\* 3. A recent survey (2024) in the vicinity of Whangārei Wharves indicates significant changes to charted depths. The most significant changes are as follows:

	Position	Depth
(a)	35°45'.052S., 174°21'.006E.	4.5
(b)	35°45'.098S., 174°21'.030E.	4.4
(c)	35°45'.099S., 174°21'.079E.	4
(d)	35°45'.133S., 174°21'.050E.	4.4
(e)	35°45'.197S., 174°21'.010E.	5.1
(f)	35°45'.757S., 174°21'.109E.	4.8

- 4. A pier in the vicinity of Whangārei Wharves has been installed with the outermost positions of: North End at 35°45'.115'S., 174°20'.954'E. and South End at 35°45'.136'S., 174°20'.959'E. Another 4 piers to the south are planned for construction.
- 5. Beacons in Kioreroa Reach have recently been replaced with buoys and a new numbering sequence.
- 6. Mariners are advised to exercise caution when navigating in the area.
- 7. Charting action will take place in due course.

Charts affected: NZ 5215, NZ 5217

Northland Regional Council HITS 5217/9, HITS 5215/184, HITS 5215/185, HITS 5217/16