

**NZ 59(T)/26      NEW ZEALAND - South Island - West Coast - Greymouth Harbour. Depths**

1. Former notice - NZ 72(T)/24 is cancelled.
2. A survey from January 2026 indicates the following least depths below CD on the bar at the Grey River/Māwheranui entrance:

| <i>Position</i>               | <i>Lead</i> | <i>Depth</i> |
|-------------------------------|-------------|--------------|
| 42° 26'.330S., 171° 11'.405E. | North Lead  | 4.3m         |
| 42° 26'.350S., 171° 11'.398E. | Main Lead   | 4.9m         |
| 42° 26'.363S., 171° 11'.396E. | South Lead  | 4.9m         |

3. Mariners should be aware that depths in Greymouth Harbour entrance are constantly changing and should contact the Port of Greymouth for the latest conditions on (03) 768 5666 or Greymouth Harbour Radio Ch14.

**Chart temporarily affected: NZ 7142**

Port of Greymouth  
HITS 7142/106